

Bay AGGREGATE, INC.

411 Tiernan Rd. • P.O. Box 1067 • Bay City, MI • 48706 • (989) 667-5990 • Fax (989) 667-5991

Date 3/23/2010 Vessel _____
 Material 29A
 State Pit Number _____
 Quarry Superior Slag
 Sample from stockpile at Bay Aggregate
 Pile Location South Side of Deck

Sieve Size	Retained Weight	Retained Percent	Cumulative % Retained	Cumulative % Passing	Specification Requirements
2 1/2 "					
2 "					
1 1/2 "	0	0.0%	0.0%	100%	
1 1/4 "					
1 "	0	0.0%	0.0%	100%	
3/4 "	0	0.0%	0.0%	100%	
1/2 "	0	0.0%	0.0%	100%	100%
3/8 "	192	9.4%	9.4%	91%	90-100%
no. 4	1653	81.0%	90.4%	10%	10-30%
no. 8	104	5.1%	95.5%	5%	0-10%
no. 16	22	1.1%	96.6%	3%	
no. 30	12	0.6%	97.2%	3%	
no. 50	8	0.4%	97.6%	2%	
no. 100	8	0.4%	98.0%	2%	
no. 200	8	0.4%	98.4%	2%	
pan	3	0.1%	98.5%	1%	3 % max
LBW	31	1.5%			
TOTAL:	2041.30	98.50%			

0.00

LOSS BY WASH **LBW MAX**

Initial Weight g
 Weight after Washing g Accepted
 Loss by Washing g Rejected _____

MOISTURE
 Rodded _____
 Initial Weight g Shoveled _____
 Dry Weight g
 Moisture g

Tested By _____

L. Philippi
 Michigan Certified Aggregate Technician
 Cert # 101992-0213